

ZoneMinder

ZoneMinder Version 1.30.4

Installed year: 2017

Installed on VM: Ubuntu Server 16 Gig RAM running on ESXI.

Model AV12186DN a.k.a AV12186 Arecont FW:65187

SourcePath Sensor

1: rtsp://xxx.xxx.xxx.xxx/h264.sdp3?res=full&x0=0&y0=0&x1=2048&y1=1536&qp=16&ssn=666&fps=2

SourcePath Sensor

2: rtsp://xxx.xxx.xxx.xxx/h264.sdp2?res=full&x0=0&y0=0&x1=2048&y1=1536&qp=16&ssn=668&fps=4

SourcePath Sensor 3:

rtsp://xxx.xxx.xxx.xxx/h264.sdp4?res=full&x0=0&y0=0&x1=2048&y1=1536&qp=16&ssn=669&fps=4

SourcePath Sensor

4: rtsp://xxx.xxx.xxx.xxx/h264.sdp1?res=full&x0=0&y0=0&x1=2048&y1=1536&qp=16&ssn=667

Capture Width: 2048
Capture Height: 1536
Garage

Model AV8185DN a.k.a AV8185 Arecont Panoramic 180 8MP = 4x 2MP FW:65187 **FW:65192 was UNSTABLE**

SourcePath Sensor

1: rtsp://xxx.xxx.xxx.xxx/h264.sdp3?res=full&x0=0&y0=320&x1=832&y1=1088&qp=16&ssn=898

SourcePath Sensor 2:

rtsp://xxx.xxx.xxx.xxx/h264.sdp2?res=full&x0=0&y0=0&x1=1600&y1=1200&qp=16&ssn=899

SourcePath Sensor 3:


rtsp://xxx.xxx.xxx.xxx/h264.sdp4?res=full&x0=0&y0=0&x1=1600&y1=1200&qp=16&ssn=889

SourcePath Sensor

4: rtsp://xxx.xxx.xxx.xxx/h264.sdp1?res=half&x0=0&y0=576&x1=768&y1=1152&qp=16&ssn=888

Capture Width: 1600,1600,1600,832
Capture Height: 1200,1200,1200,768
Backyard

Arecont tools:



MAC	FW Version	IP	Model	Status	HW Version
<input type="checkbox"/> 001A070AE5B3	65200	0.41	AV20185DN	Accessible	/
<input type="checkbox"/> 001A070C3801	65187	0.40	AV12186DN	Accessible	15749/6075
<input type="checkbox"/> 001A070ACF9D	65187	0.42	AV8185DN	Accessible	64611/65168

Total Cameras: 3 Master Password is off Auto-Discover is on = Newly added camera

Model AV20185DN a.k.a AV20185 Arecont FW:65200

SourcePath Sensor

1: rtsp://xxx.xxx.xxx.xxx/h264.sdp3?res=full&x0=0&y0=0&x1=1280&y1=960&qp=16&ssn=779

SourcePath Sensor

2: rtsp://xxx.xxx.xxx.xxx/h264.sdp2?res=full&x0=0&y0=0&x1=1280&y1=960&qp=16&ssn=778&fps=3

SourcePath Sensor 3:

rtsp://xxx.xxx.xxx.xxx/h264.sdp4?res=full&x0=0&y0=0&x1=1280&y1=960&qp=16&ssn=780&fps=2

SourcePath Sensor

4: rtsp://xxx.xxx.xxx.xxx/h264.sdp1?res=full&x0=0&y0=576&x1=640&y1=1536&qp=16&ssn=777

Capture Width:1280,,640
Capture Height: 960,960
Front

Model: WANSVIEW Pro HD 1080P Pan/Tilt WiFi Camera Q1
FW: 00.01.01.0042 2016-06-10 09:23

rtsp://admin:Password@xxx.xxx.xxx.xxx/live/ch0

Capture Width: 1920
Capture Height: 1080

Arecont : Buggy firmware !!! That's all I have to say!

All tools are located here: \Program Files (x86)\Arecont Vision\AvIpUtility\